



O-RING
 P/N P11000-113
 REPLACES P/N 12-6227N011
 QTY: 2



O-RING 90 SHORE
 P/N P11003-110
 REPLACES P/N 12-6227N008S
 QTY: 2



O-RING
 P/N P11000-011
 REPLACES P/N 12-6227N006
 QTY: 1



GASKET
 P/N 11-5028N000
 REPLACES P/N 10-450-28
 QTY: 1




RETAINING RING
 P/N P10202-050
 REPLACES P/N 12-R050S000
 QTY: 1



TEFLON BACK LIP
 P/N P11227-011
 REPLACES P/N 12-8774T006
 QTY: 2



HELICAL SPRING LOCK WASHER
 P/N P10212-025
 REPLACES P/N 12-5001C407
 QTY: 1



PISTON BUMPER
 P/N 11-5051P000
 REPLACES P/N 10-450-51
 QTY: 1

1. COMPONENT PICTURES ARE FULL SCALE
 DO NOT REDUCE OR ENLARGE WHEN MAKING COPIES OF THIS DOCUMENT



SC HYDRAULIC ENGINEERING CORPORATION
 BREA, CA 92821

HYDRAULIC REPAIR KIT P/N 11-5148N160
 REPLACES HYDRAULIC REPAIR KIT P/N 10-450-148-16